

FIG. 2




FIG. 3a







FIG. 3b










FIG. 5




FIG. 7




FIG. 8a PRIOR ART




FIG. 8b PRIOR AR




FIG. 8c PRIOR ART





FIG. 8d PRIOR AR







FIG. 10 PRIOR ART



FUNCTION OF O AND I AS INDICATED ON DIAGRAM FOR ADHESION, PENETRATION, AND SPREADING, RESPECTIVELY

FIG. IIa PRIOR ART




FIG. 11b PRIOR AR'




FIG. IIC PRIOR ART






FIG. IId PRIOR ART








FIG. 13a




FIG. 13b

× .





FIG. 13c



IG. 14




FIG. 15a




FIG. 15b




FIG. 15c




FIG. 15d




FIG. 15e




FIG. 15f






FIG. 15g




FIG. 15h




FIG. 15i